




ColorDry XL3000


Ultimate Safety



Maximized Productivity

Optimized Quality














Flexo inks dry by evaporation and unless this process is accelerated through the use of dryers, ink will not trap color on color and will mark when in line die cutting and or passing over stacker belts. Dryers accelerate the drying process, eliminating these issues, optimizing printing quality and productivity





So why ColorDry XL3000 IR dryers?

THE SAFEST IR DRYER

- All surfaces below auto ignition temperature of paper.
- With Sentinel Technology


SAFETY

THE HIGHEST PERFORMANCE IR DRYER

- High Speed Printing, Die Cutting and Finishing In a Single Pass.
- Improved ink on-press stability

OPTIMIZED QUALITY

- Dry trapping for improved color brilliance and quality
- Minimized or eliminated tracking, marking, smearing & ghosting.
- Significant reduction of waste.









Safe operation while leveraging the Power & Performance of high speed IR





- Lamps off in less than 1-second
- Lamps on in less than 1-second

Safe Operating
Temperatures

- All Surfaces below auto ignition temperature of paper
- Auto ignition Temp of Paper 217-246°C (424-475°F)

Prevention Inspection

- Sentinel Automatic Sheet Detection
- Dryer Lead Edge Sheet Detection Where appropriate
- VisionMaster Dryer Monitoring

Process Control

- Data Logging => Where + When + Who
- Report




























SENTINEL[™] - Maximized Safety & Accountability

LED Light Curtain - Sensing Any Intrusion

- Entire coverage of the drying surface
- 5mm Above guide rails / glass

Flutter Effect End Caps - Ensuring Sentinel Paper Debris Detection.




















• RFID – Reset Key for Accountability & Reporting



What, Where, When occurred



• Accountability – Who and When



Comprehensive reporting



(R.) 8/90 Bander 0 (R.) 8/90 Bander 0 (R.) 8/90 Bander 0 (M.) 8/90 Bander 0 (R.) 8/90 Bander 0	0 0	0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0	0	15	211	150	200			Name Mike	
153 8730 Rander 0 154 8730 Rander 0 155 6730 Rander 0 156 6730 Rander 0 157 6730 Rander 0		0 0	0	8					26	4	Mike .	
R4 RFID Render		0 0	-	8	0	160						
195 6FID Render 0 195 6FID Render 0 197 6FID Render 0		0 0	0				200	200	24	.4	Joseph	
ING NEW Render 0	0	HEAD PROPERTY	. 0		- 8	240	300	200	24	•	Doe	
(K7 9F)O Reader 0	-	-		11	-	.0	0	0.	0	Ð	Operator 5	
		0.8.0			10		0	0	q.	0	Operator 6	
IRS RFID Reader (4)		0 0		E4		0	0.	0	0	0	Operator 7	
		0 0		110	- 10	.0	D	0	12	a	Operator 6	
HMC RFID Reader 1	1	0 0	0	11		10	0.	0		D	Operator 9	
ME SERVICE TO DOUGH					10	- 0	- 6	0.1	g.	.6	Operator 16	
Tives Data	Test	- (11)		2562								
L. HORSO AM SYRDRIN		ke 211 t										
1.10/29/27 AM 5/10/2008		set when										
LINDOWNAM SUDONIA	DOC - 16	elet sittles kn 201 i	00E, FK 501-240	24 4								
ALTEROPEINA NECOSTA	104 - HI	let 201 1	10.212	24 /4								
		in 1803										
1 поснован упрови		6 1602 in 15.2										
		m 150										
L. DOUGHOU AN STEEDING												

3	Hine	Date	Marie Total
	133011446		TO SECURIOR FAIO:
	10:2534.49		
	331227-94 RM		
	19.37.14.69 19.37.34.69	SANOWA:	T 0845-040-0000/MAX
	20/20/24 485		
	10/2/24 88		
	10:07:04 MW		
	10:23:53 apr		
	\$5122.46 ARK	NWHIE	(I. ID SENTING HOST CATAIN HART
	\$10 (to sell sells	Makan	3 BOH SENTING LIGHT CHONOLINAT
			AND DESCRIPTION OF THE PARTY OF
			*** ADDITION FAMILY TRADITION ***
	144		
		Test	The state of the s
			as School and
			The state of the s
			The state of the s
102			The state of the s



Safety & Performance











SENTINEL[™] - Maximized Safety & Accountability

- LESD Lead Edge Sheet Detection
- Detecting Wrapped Sheets
 - For Fixed Frame Machines











Safety & Performance








SENTINEL[™] - Maximized Safety & Accountability

- LED Light Curtain
- RFID Reset
- LESD Lead Edge Sheet Detection



Detection and Suppression Partnering to Optimize Safety





Safety & Performance





VISIONMASTER – In Press Dryer Inspection and Monitoring

- Remote RFID Reset (Not Available on All Machines)
- Real Time Dryer Inspection & Monitoring
- Digital Video Recording
 - Incident History Review













JB MACHINERY

VisionMasterTM & XL3000 Control Console


VisionMaster Monitor

Diagnostic Beacon Green – Dryer ready Amber – Dryer not ready

HMI operator interface

Supplied with PC mouse and keyboard

PC for VisionMaster and Digital Video Recording



Safety & Performance





Intelligent Power Management

COLOR SELLS

Power Monitoring and Reporting

Features

• Records and Reports Power Consumption by Order



Advantage

- Records Cost to Power the Dryers for Specific Orders
 - Records: Job Number / Date Run / Job Duration



Benefits

- Accurate Cost Estimating by Order
- Reduction in Operational Costs










VISIONMASTER:

In Press Dryer Inspection and Monitoring

INTELLIGENT POWER MANAGEMENT:

In Press Dryer Inspection and Monitoring



Dryer Inspection and Power Monitoring, Partnering to Optimize Performance





State Lower





































Trends & Challenges




















Promote and Protect







Trends & Challenges


Inside Outside RDC












Bottom Top Printing





Promote and Protect







Drying: Top and/or bottom printing in-line and the need for drying.

Productivity / Quality – Dryers make it possible to run at stated press speeds when printing white top, semi or fully coated papers (see JB Fine Printing Guidelines).

Productivity / Quality – Anvil cover marking and smearing is very common when printing on all papers if dryers are not employed – leading to excess downtime for cleaning/grinding.

Quality – Ink color vibrancy and gloss will be greatly enhanced when using dryers.

Quality – Without dryers the colors can bleed causing color bleed at the ink traps

Drying: Top and/or bottom printing in-line and the greater need for drying.

It is vital that the top printed colors are fully dried before passing to the bottom print stations to avoid smearing or marking from the vacuum transfer plates.

It is vital that the top printed colors are fully dried to avoid the potential of ink build-up on die cutting knives potentially causing sheet jams, dirty cutting and marking.

It is vital that the top printed colors are fully dried to avoid the potential of die cut ejection rubbers marking and defacing the printed work, due to the stresses created at the ink surface when die cutting.







Trends & Challenges

Inside Outside 2 over 4-UV RDC



















JB MACHINERY



Drop In and Stand Out

New Drop-In Products Increase Performance and Expand Offerings










KomandCenter


Optimizing the Process

a fully comprehensive control interface



JB Centralized Equipment Control Dashboard












a fully comprehensive control interface

JB Centralized Equipment Control Dashboard













Thank you for your time!

